

# Produktrückrufe von MARES und DACOR (per eMail am 22.12.2005)/

## URGENT SAFETY NOTICE REGARDING

> **DACOR DARWIN AIR, DACOR DARWIN CONSOLE and MARES M1  
> DIVE COMPUTERS!**

> If you have recently purchased a Dacor Darwin Air or  
> Darwin Console or Mares M1 dive computer, please  
> read the following safety notice regarding the  
> recall of certain computers. HTM Sport S.p.A.,  
> Manufacturer of Dacor and Mares Dive Computers, has discovered that  
> during production, a small number of Dacor Darwin and Mares M1 dive  
> computers were improperly calibrated, resulting in erroneous  
> calculations displayed regarding "No Dec Time",  
> "Deco Time", "Air Time", "Desat Time" and "No Fly"  
> times.

>  
> The specific products that may have this defect are  
> in the following groups: Darwin Air, Darwin Console  
> and Mares M1 Dive Computers.

>  
> THE MARES M1 RGBM MODEL IS NOT INVOLVED.

>  
> a.. **DARWIN AIR: Serial Numbers between 3265 and  
> 3415**

> b.. **DARWIN CONSOLE: Serial Numbers between 8503  
> and 8592**

> c.. **MARES M1: Serial Numbers between 22783 and  
> 22902 Serial Numbers between 23019 and 23045**

> **IF YOU ARE THE OWNER OF ONE OF THE DIVE COMPUTERS  
> WITH A SERIAL NUMBER LISTED ABOVE,**

>  
> **DO NOT USE IT!**

>  
> DIVING WITH AN IMPROPERLY CALIBRATED DIVE COMPUTER  
> WILL PROVIDE INACCURATE NO DECOMPRESSION TIME,  
> DECOMPRESSION TIME, AND NO FLY TIME, AND COULD  
> RESULT IN SERIOUS INJURY, INCLUDING DECOMPRESSION  
> SICKNESS, FROM OMITTED OR UNCORRECT DECOMPRESSION!

>  
> **Take your dive computer IMMEDIATELY to your  
> Authorized Dacor or Mares Dealer for repair. You  
> should expect to receive it back within 60 days.**

>  
> We regret any inconvenience caused by this recall  
> and thank you in advance for your cooperation.

>  
> HTM Sport S.p.A.

>  
> Rapallo, December 14, 2004